

Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mesa VI Mine AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I Site Identification, Location and Status

Site Names and ID numbers as applicable

Mine ID: 611

Map ID: N204

CERCLIS: NNN000908920

Navajo Abandoned Mine Land Reclamation Program: NA-0319

Local name / Aliases: Mesa 6 Mine

Chapter and local area: Cove Chapter

Lat/Long: 36.5428608766 N / -109.258270605 W

Local Post Office: Cove, AZ

Surface Land Status: check one or more and provide ownership and contact information below

Tribal Trust Land
Private
Bureau of Land Mgmt
State

Public lands
Tribal Fee Land
Allotment
Fee land

Subsurface Mineral Rights:

No information on subsurface mineral rights ownership was found in the EPA/AUM Database.

Claim and operator information:

The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Kerr-McGee from 1961 to 1962, and Vanadium Corp. of America in 1964. No other historical ownership / lease information was identified in the EPA/AUM database.

Number of residential structures within 200 feet of mine:

None

Estimated volume of mine waste onsite:

2,315 yd^3

Part II Summary of radiological readings

Highest gamma radiation measurement:

655,527 counts per minute (cpm)

Describe any other radiological measurements:


A total of 1,817 gamma radiation measurements were collected from the mine site, ranging from 10,135 cpm to 655,527 cpm. Measurements in the vicinity of the waste debris were found at levels in up to 150,000 cpm, and at the sealed adit at levels up to 650,000 cpm. Due to poor satellite coverage, the gamma reading locations were not mapped by the GPS. A site layout is shown in Figure 1.

Background Locations
#1 14,096 cpm

Average background = 14,096 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



Count:	1817
Minimum:	10135.00000
Maximum:	655527.00000
Sum:	65679949.00000
Mean:	36147.46780
Median:	18401.00000
Standard Deviation:	41772.03878

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed : Yes Waste Pile onsite : Yes

NAMLRP Project Number: NA-0319

NAMLRP Mine features: 3 Portals

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits

One sealed adit; two open inaccessible adits

Waste Piles

Waste piles extending down slope to creek, 250' x 50', with a total estimated volume of 2,315 yd³

Pits

None

Shafts

None

Other Debris and Mine Features

Mining tracks and rails extending from adits

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Mesa VI Mine consists of an area of 15,955.06 m². The mine was identified as being operational from 1961 to 1964. Historical documents showed the operator of the mine as Kerr-McGee from 1961 to 1962, and Vanadium Corp. of America in 1964. While operational, the mine had a total reported production volume of 8,994 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Mesa VI Mine **Chapter:** Cove

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

1 sealed adit; 2 inaccessible open adits with mining debris; unreclaimed waste pile

Part VI Photos



Photo 1. Cliffside adits




Photo2. Tracks protruding from adit



Photo 3. Cliffside open adits




Photo 4. Waste pile



Photo 5. Cliff area



Photo 6. Sealed adit



Photo 7. Sealed adit



Photo 8. Mine site

Part VII Contacts Reports and InformationName: Stanley Edison (928) 871-6861Eugene Esplain (928) 871-7331Title or official role (if any) Navajo EPA Superfund ProgramAddress PO Box 2946, Window Rock, AZ 86515Information provided Lead Regulatory Agency

Name_____

Title or official role (if any) _____

Address_____

Telephone number_____

Information provided_____

Name_____

Title or official role (if any) _____

Telephone number_____

Information provided_____

Name_____

Title or official role (if any) _____

Telephone number_____

Information provided_____

Figure 1 - Gamma Radiation Measurements
Mesa VI Mine (611)
Cove Chapter, Navajo Nation, Arizona



Note: Poor satellite coverage was encountered throughout the site.
The site readings were not located by the GPS, but are included in the screen report.

Legend

Gamma Radiation Measurements

- 0 - 10,000
- 10,000 - 15,000
- 15,000 - 20,000
- 20,000 - 50,000
- 50,000 - 100,000
- > 100,000



Observed Adit

Observed Waste Pile



Inaccessible due to steep grades



General Direction Down-Slope



Mine Claim Boundaries

Gamma survey conducted 10/2009
Measured as counts per minute (cpm)

Average background 14,096 cpm



0 150 Feet



WESTON
SOLUTIONS